



HOT WATER DISTRIBUTION BASINS

**For All Crossflow Cooling Towers,
Fluid Coolers, and Evaporative Condensers**



Extend Equipment Life

Replace corroded hot water basins to extend the life of your equipment without the expense of replacing the unit.

Improve Thermal Performance

Missing and clogged nozzles reduce thermal performance. New hot water basins will restore proper water distribution.

Custom Design

Hot water distribution basins are custom engineered for all competitors' units.

Complete Installation Kits

Kits include nozzles, covers, hardware, sealer tape and instructions. Kits are available knocked-down for easy field assembly or factory assembled. Materials of construction are G-235 galvanized or 304 or 316 stainless steel.

Quick Shipment

Standard availability is 3 weeks. Quicker deliveries are always available when needed.

Call **EVAPCO** at **410-756-2600** for the Mr. GoodTower® Service Center or Representative near you.

Do Your Hot Water Distribution Basins Look Like This?



Deteriorated Hot Water Distribution Basins Will Result In:

- Leaks - increased water and chemical costs!
- Clogged nozzles – decreased thermal performance!
- Missing nozzles – decreased thermal performance!



Mr. GoodTower®



For A Free Unit Inspection Contact Your Local
Mr. GoodTower® Service Center or Representative at:



Call EVAPCO at 410-756-2600 for the Mr. GoodTower® Service Center or Representative near you.